

Water Quality Chemistry Services Lead School Testing Report Date: 6/7/17

San Diego Unified School District **Dewey Elementary**

	Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
_	W1173073	05/24/17	05:51 AM	SAMPLE 1	3710020-CAB-A	< 5	ug/L
	W1173074	05/24/17	05:54 AM	SAMPLE 2	3710020-CAB-B	< 5	ug/L
	W1173075	05/24/17	06:01 AM	SAMPLE 3	3710020-CAB-C	< 5	ug/L
	W1173076	05/24/17	05:57 AM	SAMPLE 4	3710020-CAB-D	< 5	ug/L
	W1173077	05/24/17	06:05 AM	SAMPLE 5	3710020-CAB-E	< 5	ug/L

Source	Source Description
SAMPLE 1	CDC, Rooms 15-22, Room 18, classroom sink/faucet, bubbler at sink
SAMPLE 2	CDC, Rooms 15-22, Wall mounted exterior (South of Bldg), next to Hallway door, facing Playground/lunch arbor, dual bubbler fountain, right bubbler
SAMPLE 3	Rooms 7-13 bldg, Wall mounted exterior (South of Bldg), next to Hallway door, facing blacktop, triple bubbler fountain, right bubbler
SAMPLE 4	Dirt Field (closer to Portable Classrooms & Restrooms), Floor mounted exterior, two fountain fixture, lower left bubbler when facing portable classrooms
SAMPLE 5	Front Office/Hallway, Wall mounted exterior (South of Bldg), facing Lunch Arbor, two single bubbler fountains, lower left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L $\,$

Doug Campbell, Senior Chemist