

Facility: Hickman ES Report Type: Progress Report Date of Report: 01/28/19

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
1	1 Admin/Supply - Hickman_01-01 Nurse Health, South side of room	DWO-201-001	Faucet	3.14		
2	1 Admin/Supply - Hickman_01-01 Faculty Workroom - WRK1, East wall	DWO-201-002	Faucet	4.87		
3	1 Admin/Supply - Hickman_01-01 Building Exterior, SW side of bldg	DWO-201-003	Drinking Fountain Bubbler	1.12		
4	1 Admin/Supply - Hickman_01-01 Building Exterior, SW side of bldg	DWO-201-004	Drinking Fountain Bubbler	2.33		
5	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Multi-Purpose - MPK1, North wall	DWO-201-005	Drinking Fountain Bubbler	1.06		
6	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Multi-Purpose - MPK1, North wall	DWO-201-006	Drinking Fountain Bubbler	0.77		
7	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Classroom - L-2 Music, West wall	DWO-201-007	Faucet	4.97		
8	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Food Services/Kitchen - FSK1, East wall	DWO-201-008	Faucet	<5		
9	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Faculty Workroom - WRK1, West wall	DWO-201-009	Faucet	9.59		
10	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, Lunch court Wall	DWO-201-010	Drinking Fountain Bubbler	<5		
11	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, Lunch court Wall	DWO-201-011	Drinking Fountain Bubbler	2.57		
12	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, Lunch court Wall	DWO-201-012	Drinking Fountain Bubbler	1.51		
13	10 Classrooms 10-16 - Hickman_01-03 Classroom - 3F Study Rm, East wall	DWO-201-013	Drinking Fountain Bubbler	3.85		
14	10 Classrooms 10-16 - Hickman_01-03 Classroom - 3D Study Rm, South wall	DWO-201-014	Drinking Fountain Bubbler	3.15		
15	10 Classrooms 10-16 - Hickman_01-03 Classroom - 3C Study Rm, South wall	DWO-201-015	Drinking Fountain Bubbler	2.80		
16	10 Classrooms 10-16 - Hickman_01-03 Faculty Workroom - WRK1, East wall	DWO-201-016	Faucet	4.13		
17	10 Classrooms 10-16 - Hickman_01-03 Classroom - 3A Study Rm, West wall	DWO-201-017	Drinking Fountain Bubbler	5.73		



Facility: Hickman ES Report Type: Progress Report Date of Report: 01/28/19

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
18	10 Classrooms 10-16 - Hickman_01-03 Building Exterior, South wall	DWO-201-018	Drinking Fountain Bubbler			
19	10 Classrooms 10-16 - Hickman_01-03 Building Exterior, South wall	DWO-201-019	Drinking Fountain Bubbler			
20	10 Classrooms 10-16 - Hickman_01-03 Building Exterior, South wall	DWO-201-020	Drinking Fountain Bubbler	5.02		
21	20 Classrooms 20-26 - Hickman_01-04 Building Exterior, West wall	DWO-201-021	Drinking Fountain Bubbler	1.34		
22	20 Classrooms 20-26 - Hickman_01-04 Building Exterior, West wall	DWO-201-022	Drinking Fountain Bubbler	<5		
23	20 Classrooms 20-26 - Hickman_01-04 Building Exterior, West wall	DWO-201-023	Drinking Fountain Bubbler	1.15		
24	20 Classrooms 20-26 - Hickman_01-04 Classroom - 4F Study Rm, South wall	DWO-201-024	Drinking Fountain Bubbler	4.55		
25	20 Classrooms 20-26 - Hickman_01-04 Classroom - 4D Study Rm, East wall	DWO-201-025	Drinking Fountain Bubbler	3.54		
26	20 Classrooms 20-26 - Hickman_01-04 Classroom - 4C Study Rm, West wall	DWO-201-026	Drinking Fountain Bubbler	3.16		
27	20 Classrooms 20-26 - Hickman_01-04 Classroom - 4A Study Rm, North wall	DWO-201-027	Drinking Fountain Bubbler	3.31		
28	20 Classrooms 20-26 - Hickman_01-04 Faculty Workroom - WRK1, South wall	DWO-201-028	Faucet	10.60		
29	30 Classrooms 31-36 - Hickman_01-05 Building Exterior, West wall	DWO-201-029	Drinking Fountain Bubbler	2.70		
30	30 Classrooms 31-36 - Hickman_01-05 Building Exterior, West wall	DWO-201-030	Drinking Fountain Bubbler	1.57		
31	30 Classrooms 31-36 - Hickman_01-05 Building Exterior, West wall	DWO-201-031	Drinking Fountain Bubbler	1.09		
32	30 Classrooms 31-36 - Hickman_01-05 Classroom - 5F Study Rm, South wall	DWO-201-032	Drinking Fountain Bubbler	3.37		
33	30 Classrooms 31-36 - Hickman_01-05 Classroom - 5D Study Rm, West wall	DWO-201-033	Drinking Fountain Bubbler	5.71		
34	30 Classrooms 31-36 - Hickman_01-05 Classroom - 5C Study Rm, West wall	DWO-201-034	Drinking Fountain Bubbler	25.10		



Facility: Hickman ES Report Type: Progress Report Date of Report: 01/28/19

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
35	30 Classrooms 31-36 - Hickman_01-05 Classroom - 5A Study Rm, North wall	DWO-201-035	Drinking Fountain Bubbler			
36	30 Classrooms 31-36 - Hickman_01-05 Faculty Workroom - WRK1, South wall	DWO-201-036	Faucet	38.00		
37	40 Classrooms 41-46 - Hickman_01-06 Building Exterior, North wall	DWO-201-037	Drinking Fountain Bubbler	0.83		
38	40 Classrooms 41-46 - Hickman_01-06 Building Exterior, North wall	DWO-201-038	Drinking Fountain Bubbler	1.20		
39	40 Classrooms 41-46 - Hickman_01-06 Building Exterior, North wall	DWO-201-039	Drinking Fountain Bubbler	<5		
40	40 Classrooms 41-46 - Hickman_01-06 Classroom - 6F Study Rm, West wall	DWO-201-040	Drinking Fountain Bubbler	2.03		
41	40 Classrooms 41-46 - Hickman_01-06 Classroom - 6D Study Rm, North wall	DWO-201-041	Drinking Fountain Bubbler	3.02		
42	40 Classrooms 41-46 - Hickman_01-06 Classroom - 6C Study Rm, North wall	DWO-201-042	Drinking Fountain Bubbler	4.19		
43	40 Classrooms 41-46 - Hickman_01-06 Classroom - 6A Study Rm, East wall	DWO-201-043	Drinking Fountain Bubbler	2.34		
44	40 Classrooms 41-46 - Hickman_01-06 Faculty Workroom - WRK1, West wall	DWO-201-044	Drinking Fountain Bubbler	2.53		
45	Portable B06 - Hickman Classroom - B06, NW corner	DWO-201-045	Drinking Fountain Bubbler	1.56		
46	Portable B05 - Hickman Classroom - B05, NW corner	DWO-201-046	Drinking Fountain Bubbler	2.09		
47	Portable B03 - Hickman Classroom - B03, SE Corner	DWO-201-047	Drinking Fountain Bubbler	2.47		
48	Portable B02 - Hickman Classroom - B02, SW Corner	DWO-201-048	Drinking Fountain Bubbler	2.27		
49	Portable B01 - Hickman Classroom - B01, SE Corner	DWO-201-049	Drinking Fountain Bubbler	13.80		
50	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, North wall	DWO-201-050	Drinking Fountain Bubbler			
51	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, North wall	DWO-201-051	Drinking Fountain Bubbler			



Facility: Hickman ES Report Type: Progress Report Date of Report: 01/28/19

	Location	DWO No	Туре	Initial Result*	Action Taken**	Clearance Result
52	2 Kitchen/Multi-Media/Multi-Purpose - Hickman_01-02 Building Exterior, North wall	DWO-201-052	Drinking Fountain Bubbler			
53	1 Admin/Supply - Hickman_01-01 Hallway by Offices/Workroom, EAST SIDE OF	DWO-201-053	Drinking Fountain Bubbler	5.59		

*Action levels and color indication

Federal action level is above 15ppb (parts per billion). SDUSD uses an action level that is stricter and includes anything above 5 PPB. Items indicated in green are below District action level. Items indicated in yellow are above District action level. Items indicated in red are above both District and Federal action levels. Green indicates no action needed. Red/Yellow indicates action needed.

**Clearance actions

INIT=Inital result cleared no action needed. FLTR=Filter has been installed. PLMB=Plumbing work performed. RRC=Repeat and repeat-confirmation testing has been performed and both samples yielded results below District action level. RMOV=The drinking water outlet has been removed from service.