

Environmental Monitoring and Technical Services 2392 Kincaid Road MS 45A. San Diego, CA 92101 Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services Lead School Testing Report Date: 6/7/17

## San Diego Unified School District Whitman Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172904	05/19/17	06:03 AM	SAMPLE 1	3710020-BJA-A	< 5	ug/L
W1172905	05/19/17	06:12 AM	SAMPLE 2	3710020-BJA-B	< 5	ug/L
W1172906	05/19/17	06:07 AM	SAMPLE 3	3710020-BJA-C	< 5	ug/L
W1172907	05/19/17	06:09 AM	SAMPLE 4	3710020-BJA-D	< 5	ug/L
W1172908	05/19/17	06:15 AM	SAMPLE 5	3710020-BJA-E	< 5	ug/L

## Source Source Description

- SAMPLE 1 Kitchen, east side, faucet over 2 compartment sink
- SAMPLE 2 Rooms 7-12 bldg, Room 7, bubbler at sink
- SAMPLE 3 Rooms 2-6 bldg, West facing wall next to Room 6, triple bubbler fountain, right bubbler
- SAMPLE 4 Rooms 13-18 bldg, East facing wall next to boys RR, triple bubbler fountain, middle bubbler
- SAMPLE 5 Kindergarten bldg, Kindergarten Play Yard, two sinhle bubbler fountains, lower left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L

Doug Campbell, Senior Chemist